

FIAT SERVICE LETTER

SUBJECT: AXLE SHAFTS

VEHICLES: 1979 X1/9 AND STRADA MODELS

SERVICE

INFORMATION: Whenever the axle shafts are removed or disconnected for repairs, the existing Allen head bolts, securing the shafts to the differential and wheel hub flanges must be replaced.

The new Allen head bolts must be torqued to 31 ft. lbs. (4.3Kgm).

PARTS

INFORMATION Allen Head bolts - Part No. 4393157 - Standard Transmission
- Part No. 4402236 - Automatic Transmission

READ, INITIAL AND PASS ON

Service Manager	Parts Manager	Service Writer	Technician				